PLAT BOOK 1
PAGE 106

Note This drawing is strictly an accordance with U.S. Field Notes and the laws and regulations of U.S. General Land Office

The 1/4 Sec post on Northy Boundary set for a Survey in Sec 10 is absolutely wrong and is not used or accepted as correct for this survey

Titusville Fla Aug 25th 1899

J O Fries
Co Surveyor

A short time after this survey the remains of the original 1/4 Sec post on the Northy boundary of Sec 15 were found and proved this survey was correct

Oct 1899 J O Fries



MAP

Showing location of Lot 2 - Section 15 - Tp 35 So - Rg. 40 E

being the property of James C. Andrews

Brevard Co Fla

Scale 10 chs to 1 inch

Surveyed Aug 1899 by J O Fries Co Surveyor

Filed for record
Oct 28th 1899
A. A. Stewart Clerk C.C.
By C R Stewart D.C.

Transcribed from the Original this 28th day of Oct 1899
J O Fries
Co Surveyor

North



South

Subdivision of
NW 1/4 of SW 1/4 of Sec. 10. T. 35. R 40 E
Surveyed by J F Bell
25 & 28 of May 1896

Filed and recorded November 5th 1896
A A Stewart Clerk by C R Stewart D C

Transcribed from plat recorded in Deedbook 18B page 747 by
J O Fries
Co Surveyor